

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 8A

9/41




FIG. 8B

10/41




FIG. 9




FIG. 10




FIG. 11




FIG. 12

14/41




FIG. 13A




FIG. 13B




FIG. 13C




FIG. 14




FIG. 14A




FIG. 15




FIG. 16




FIG. 17




FIG. 18




FIG. 18A




FIG. 19





FIG. 20



* Note: Only either the fax data transmitter or receiver is operating at anytime

FIG. 21

REPLACEMENT SHEET
(09/533,022)
(March 22, 2000)

27/41




FIG. 22




FIG. 23




FIG. 24




FIG. 25




FIG. 26




FIG. 27





FIG. 28






FIG. 30




FIG. 31

37/41




FIG. 32





FIG. 33

700



Timing Frequency
Offset Estimate

FIG. 34




FIG. 35




FIG. 36